STAT	Approved For Release 2005/11/21 : GIA-RDP78B0477 202905020053-2	
*	Approved For Release 2005/11/21 GASKISF 78B0477 19506020053-2 August 17, 1964	STAT
	File Protection Committee	STAT
Q	DIGITAL READOUT COUNTERS	
	There is some confusion as to which Model Counter is to provide on the current order. There were two models made on the previous order. They were:	STAT
	Previous Order for Two 2-axis Counters	
• STAT	1. One each Model 2825A Control Panel One each Model 2827A Synchronizer Two each Model 2826A Counter with input amplifier, with 5-volt lamp power output connector, and with a multipin output connector for 15EL44 amplifier power for the sensing head.	
STAT	2. One each Model 2825A Control Panel One each Model 2827A Synchronizer Two each Model 2826B Counter with input amplifier for the sensing head and with no extra power output connectors.	
	The Present Contract for Three 2-axis Counters	
STAT	One each Model 2825A Control Panel One each Model 2827A Synchronizer Two each Model 2826B Counter with input amplifier for the sensing head and with no extra power output connectors.	
STAT	This is what is being built and this is what requires, however, the contract calls for Model 2826A counters. A contract change is required and I understand is preparing to issue a change.	STAT
STAT	The present contract for one 4-axis counter is denoted the Model 2826C with input amplifier, with 5-volt lamp power connector, and with a multipin connector for 15EL44 amplifier power for the head. The Model C is the same as the Model A but is configured differently due to the different physical arrangement. Also, the zero reset and preset reset pushbuttons have been deleted. The functions will be controlled remotely by customer equipment.	

Declass Review by NGA.

Digital Readout Counters

STAT

STAT

STAT STAT 17 August 1964

The situation was hopelessly confounded last week when erroneously told me the opposite. He had said on August 10 that the 2-axis was being built for the heads and the 4-axis was being built for the head. This information naturally confused John when I reported it in my last report.	
As of this morning (Monday), had not received the two data phones or the data phone data sent by John last Friday. had, however, obtained the data from	STA
the local rep. cannot tell as yet what the interlock problem is. They may, however, find the answer when they get the data phones. They can undoubtedly find the problem when they operate the 2-axis system now being completed with a data phone. Sending the data phones to was a sound action in my opinion.	STA STA
For the first 2-axis system, the counters were completed and are being checked out by The control panel is completely assembled and wired. The synchronizer wiring is nearly done and will be completed by tomorrow. Checkout of the chassis will continue through the week.	STA